




1




2





3




4



5




①x1




② x2




③ x1




④ x1




⑤x2




⑥x1




⑦x1




⑧x1




⑨x1




⑩ x1



⑪x2



⑫x2



Ax13



Bx13



Cx14



Parker screw
50MM

Dx6



M6 30MM

Ex8



Parker screw
15MM

Fx1

